

# SERVICE BULLETINEII

SB No.

55

Issue No.

TITLE

SPECIAL INSPECTION OF THROTTLE CABLE - T67 GRP AIRCRAFT EXCEPT T67C

CLASSIFICATION

This Service Bulletin has been classified as mandatory by the U.K. C.A.A.

COMPLIANCE

Mandatory Modification M496 must be incorporated not later than July 31st 1994.

This Service Bulletin supersedes and replaces Mandatory S.B. Nos 40 and 41.

### APPLICABILITY:

All T67B, T67C(Pre Mod 480), T67M, T67M MKII, T67M200 alrcraft.

### **INTRODUCTION:**

There have recently been cases of breakage of the throttle cable on T67 g.r.p. alrcraft. In these cases the cable has broken at the cockpit end at a point where the inner cable emerges from the outer cable, see Figure 1.

Slingsby Avlation are developing a Modification (Mod M496) which will be applicable to all T67 g.r.p. aircraft which will incorporate an improved fixing of the throttle cable at the cockpit end. Details of Mod M496 will be sent to all Service Bulletin addressees as soon as the modification is available. Incorporation of Mod M496 will discharge the requirements of this Service Bulletin; meanwhile the inspections below are to be carried out as detailed.

#### **ACTION - FIRST INSPECTION**

- 1. Set the throttle lever to the idle position, and measure the clearance at the idle stop screw.
- 2. Slacken cable clamp bolt, and disconnect the throttle cable at the carburettor/fuel injector.
- Withdraw the cable about 2 cm. this ensures that all the affected part of the inner cable will be visible.
- Visually examine the inner cable for evidence of kinking or cracking if either is found the cable must be replaced.

1 9 APR 1994

ISSUED BY:					/ ,		
	J. Bal.		Date	14	/4/	94	
favor to the first							
	INGSBY AVIATION LIMITED	Tel 0751 32474 Telev 57597	Page	1	of	3	

MTP 231

1 / 92



# SERVICE BULLETIN ATTI

SB No.

55

Issue No.

- 1

TITLE

# SPECIAL INSPECTION OF THROTTLE CABLE - T67 GRP AIRCRAFT EXCEPT T67C

#### CONTINUED

- 5. Check that the length of the outer cable which extends aft beyond the "P" clip, is between 0 and 2 cm. If necessary, adjust the cable position to lie within this tolerance by slackening the "P" clip, repositioning the cable, and retightening the "P" clip. It may be necessary to also adjust the outer cable clamp position at the engine end of the cable. When retightening the "P" clip, ensure that it is angled to equalize sideways bending of the inner cable during operation.
- 6. Set the carburettor/fuel injector to the idle position, and the left hand throttle lever to the position measured in 1. above; retighten the cable clamp bolt.
- Adjust the full throttle clearance, measured at the throttle lever stop screw, to no more than 1 mm., ensuring that the throttle inner cable between the outer cable termination and the cable clamp bolt is not bowed.
- 8. Adjust the idle clearance, measured at the throttle lever stop screw to no more than 1 mm.
- N.B. The action of the throttle cable on T67M and T67M MKII aircraft is the reverse to all other T67 aircraft, and the requirement to ensure that the inner cable is not bowed will apply at the idle position.
- N.B. Worn linkages in the throttle cross shaft assembly should be replaced (play in this assembly would allow the centre throttle action to cause bowing of the inner cable despite correct setting of the throttle stops on the left hand throttle lever).
- N.B. If any difficulty is found in limiting the throttle lever clearance to 1 mm. check that the throttle stop screws have an effective length of 25 mm. If any are found which have an effective length of 20 mm. contact the Customer Service Department.

## **ACTION - REPEAT INSPECTIONS**

Carry out items 1,2,3,4, and 6 as detailed above. Check that the clearance as measured at the throttle lever stop screws is no more than 1 mm. at Idle and at full throttle.

Approved: 5.73 | Date: 14/4/94 | Page 2

3

of



