



## Information Bulletin

I.B. No: 040

Aircraft Type:

T67B, T67C Series, T67M, T67M-MKII, T67M260 & T67M260-T3A.

Title:

AVAILABILITY OF MOD KITS FOR "MOD M988B INTRODUCTION OF REVISED TAILPLANE

MOUNTING BRACKETS, TAILPLANE MOUNTED".

This Information Bulletin is issued to inform customers of the availability of the Mod Bulletin for Mod M988B "Introduction of Revised Tailplane Mounting Brackets, Tailplane Mounted" and it's Mod Kit T67A-05-988B.

The incorporation of this Modification removes the requirements for repetitive inspections of the Aluminium Alloy type brackets as specified in Mandatory Service Bulletin SB179, (EASA AD 2005-564 refers). The new Post Mod M988B brackets are manufactured from Titanium material.

For Modification availability, delivery and cost please contact SACL Customer Support Department or email Kathy Cooper on <a href="mailto:kathy.cooper@slingsby.co.uk">kathy.cooper@slingsby.co.uk</a>.

Signature	Signature Design CVE	Signature	Slingsby Approval
Print Name M. J. Rutter	Print Name N. THORP	Print Name	D.W. GODDOO
Date 6 <sup>th</sup> August 2007	Date 4-9-07	Date	5-9-07
SLINGSBY ADVANCED COMPOSITES LIMITED Kirkbymoorside, York. YO62 6EZ Tel: 01751 432474 Fax No: 01751 433016 Tel: mike.rutter@slingsby.co.uk		Page 1	of 1 Issue 1